



Figure 2.6-23 Inspection Opening No. 4

- e. Asphalt mopping layer.
- f. Approximately 1/2-inch thick layer (tapered) All-Weather Crete asphalt/perlite fill (wet).
- g. Approximately 1-1/2-inch thick layer of composite bitumen-aggregate fill (wet).
- h. Approximately 1/8-inch thick layer of asphalt.
- i. Concrete roof slab.

2.6.2.5 Inspection Opening No. 5. The fifth inspection opening was made at a ridge in the existing roofing membrane and along a building column line. The existing construction at this location varied within the area exposed as noted below.

On the east side of this opening, the existing construction consists of the following (from top to bottom):